Short Instructions

Spectroradiometer

specbos 1211

JETI Technische Instrumente GmbH
Tatzendpromenade 2
D-07745 Jena
Tel. +49-3641-225 680
Fax. +49-3641-225 681
e-mail: sales @ jeti.com
Internet: www.jeti.com

License Agreement for JETI Technische Instrumente GmbH Software Products

IMPORTANT -- READ CAREFULLY BEFORE USING THE JETI SOFTWARE

JETI hereby grants to you a non-exclusive license to use one copy of the delivered JETI software program (the "software") on a single computer according to the following items: The software is in "use" on the computer when it is loaded into temporary memory (i.e. RAM) or installed into permanent memory (e.g. hard disk, CD-ROM, or other storage device) of the computer. However, installation on a network server for the sole purpose of distribution to one or more other computer(s) shall not constitute "use" for which a separate license is required, provided you have separate license for each computer to which the software is distributed.

It is only allowed to use the software in connection with the JETI product (instrument, spectrometer or OEM electronics), which was delivered with this software. For additional JETI products you need an extra software license.

The software is owned by JETI or its suppliers and is protected by German copyright laws and international treaty provisions and all other applicable national laws. Therefore, you must treat the software like any other copyrighted material (e.g. a book or musical recording) except that if the software is not copy protected you may either

(a) make one copy of the software solely for backup or archival purposes, or
(b) transfer the software to a singlehard disk provided you keep the original solely for backup or archival purposes. You may not copy the user documentation provided with the software and the connected JETI product.

You may not:

(i) permit other individuals to use the software except under the terms listed above;
(ii) modify, translate, reverse engineer, decompile, disassemble (except to the extent that this restriction is expressly prohibited by law) or create derivative works based upon the software or documentation;
(iii) copy the software or documentation (except for back-up or archival purposes);
(iv) rent, lease, transfer, or otherwise transfer rights to the software or documentation;
(v) remove any proprietary notices or labels on the software or documentation.

Any such forbidden use shall immediately terminate your license to the Software.

(a) You agree that you shall only use the software and documentation in a manner that complies with all applicable laws in the jurisdictions in which you use the software and documentation, including, but not limited to, applicable restrictions concerning copyright and other intellectual property rights.
(b) You may not use the software in an attempt to, or in conjunction with, any device, program or service designed to circumvent technological measures employed to control access to, or the rights in, a content file or other work protected by the copyright laws of any jurisdiction.
(c) If you receive the first copy of the software electronically and a second copy on physical media (e.g., CD, diskette, etc.), the second copy may be used for archival purposes only and may not be transferred to or used by any other person. This license does not grant you any right to any enhancement or update.

The software may include certain external software components ("Add-Ons"), including the Lab Windows user interface and drivers. You may only call to or otherwise use such Add-Ons through the use of the JETI applications. Any direct use of Add-Ons through a non-JETI proprietary application, including a custom or user-written application is prohibited by this Agreement.

If you have purchased JETI software in connection with a JETI product, you have the right of purchasing a software update, if it is available, for a priority price.

Title, ownership, rights, and intellectual property rights in and to the software and documentation shall remain in JETI and/or its suppliers. Title, ownership rights and intellectual property rights in and to the content accessed through the software including the content contained in the software media demonstration files shall be retained by the applicable content owner and may be protected by applicable copyright or other law. This license gives you no rights to such content.

For the JETI operating environment, the following terms apply:

JETI warrants that for a period of ninety (90) days from the date of acquisition the software, if operated as directed, will substantially achieve the functionality described in the documentation. JETI does not warrant however that your use of the software will be uninterrupted or that the operation of the software will be error-free or secure. JETI also warrants that the media containing the software, if provided by JETI, is free from defects in material and workmanship and will so remain for ninety (90) days from the date you acquire the software.
To the maximum extend permitted by applicable law JETI and its suppliers disclaim all other warranties either express or implied including but not limited to implied warranties of merchantability and fitness for a particular purpose with regard to the software, the accompanying written materials and any accompanying hardware.
If the media is subjected to accident abuse or improper use during the warranty period; or if you violate the terms of this License Agreement, this warranty shall immediately terminate. This warranty shall not apply if the software is used on or in conjunction with hardware or software other than the unmodified version of hardware and software with which the software was designed to be used as described in the documentation.
This limited warranty gives you specific legal rights.
Your remedies:
JETI's sole liability for a breach of this warranty shall be in JETI's sole discretion:

(i) to replace your defective media; or
(ii) to advise you how to achieve substantially the same functionality with the software as described in the documentation through a procedure different from that set forth in the documentation; or
(iii) if the above remedies are impracticable, to refund the license fee, if any, you paid for the software. Repaired, corrected or replaced software and documentation shall be covered by this limited warranty for the period remaining under the warranty that covered the original software or if longer for thirty (30) days after the date JETI either shipped to you the repaired or replaced software or advised you as to how to operate the software so as to achieve the functionality described in the documentation, whichever is applicable. Only if you inform JETI of the problem with the software during the applicable warranty period and provide evidence of the date you acquired the software will JETI be obligated to honor this warranty.

Under no circumstances and under no legal theory whether in tort contract or otherwise shall JETI or its suppliers or resellers be liable to you or any other person for any indirect, special, incidental or consequential damages of any character including without limitation damages for loss of goodwill, work stoppage, computer failure or malfunction or any and all other commercial damages or losses even if JETI shall have been informed of the possibility of such damages or for any claim by any other party. Further, in no event shall JETI´s liability under any provision of this agreement exceed the license fee paid to JETI for the software and documentation.
This software is intended for use only with properly licensed media, content, and content creation tools. It is your responsibility to ascertain whether any copyright, patent or other licenses are necessary and to obtain any such licenses to serve and/or create, compress or download such media and content. You agree to record, play back and download only those materials for which you have the necessary patent, copyright and other permissions, licenses, and/or clearances. You agree to hold harmless, indemnify and defend JETI, its officers, directors and employees, from and against any losses, damages, fines and expenses (including attorneys' fees and costs) arising out of or relating to any claims that you have

(a) viewed, downloaded, encoded, compressed, copied or transmitted any materials (other than materials provided by JETI) in connection with the software in violation of another party's rights or in violation of any law, or
(b) violated any terms of this License Agreement.

This License Agreement will automatically terminate if you fail to comply with any term hereof. No notice shall be required from JETI to effect such termination.

Technical support for the software, as made available by JETI, is given directly from the JETI office in Jena, Germany.
This License Agreement shall constitute the complete and exclusive agreement between JETI, it's resellers and the end user, notwithstanding any variance with any purchase order or other written instrument submitted by you, whether formally rejected by JETI or not. The acceptance of any purchase order you place is expressly made conditional on your consent to the terms set forth herein. The terms and conditions contained in this License Agreement may not be modified except in a writing duly signed by you and an authorized representative of JETI. If any provision of this License Agreement is held to be unenforceable for any reason, such provision shall be reformed only to the extent necessary to make it enforceable, and such decision shall not affect the enforceability of such provision under other circumstances, or of the remaining provisions hereof under all circumstances. This License Agreement shall be governed by the laws of Germany, without regard to conflicts of law provisions, and you hereby consent to the exclusive jurisdiction of the provincial and federal courts sitting in Germany. Any and all unresolved disputes relating in any way to, or arising out of, the software, your use of the software or this License Agreement shall be submitted to arbitration in Germany; except that, to the extent that you have breached or have indicated your intention to breach this License Agreement in any manner which violates or may violate JETI's intellectual property rights, or may cause continuing or irreparable harm to JETI (including, but not limited to, any breach that may impact JETI's intellectual property rights, or a breach by reverse engineering), JETI may seek injunctive relief, or any other appropriate relief, in any court of competent jurisdiction.

Copyright (c) 2012 JETI Technische Instrumente GmbH and/or its suppliers.
JETI Technische Instrumente GmH, Tatzendpromenade 2, 07745 Jena, Germany. All rights reserved.

Table of Contents

1. Introduction 9

2. Operation of Device 11

2.1. specbos 1211 11

2.2. specbos 1211-BT 11

3. Installation of Hardware 13

3.1. Installation of USB Device 13

3.2. Installation of Bluetooth Device (specbos 1211 BT) 13

3.3. Installation of RS Device (specbos 1211 RS) 17

3.4. Network settings for specbos 1211 LAN 17

3.5. Installing RealPort Driver 19

3.6. Installation of Driver Software 22

3.6.1 Installation under Windows XP 22

3.6.2 Installation under Windows Vista and Windows 7 23

3.7. PC- Software 24

3.7.1 Installation under Windows 24

4. Start the Software 25

5. Measurement 27

5.1. Procedure 27

5.1.1 Measurement with specbos 1211-BT 28

5.1.2 Finishing the Program 30

6. Software Settings 31

6.1. Measurement Settings 31

6.1.1 Integration Time 31

6.1.2 Continuous measurement 32

6.1.3 Change measurement name 32

6.1.4 Delete Measurements 34

6.1.5 Calculation Range 34

6.2. Display Settings 35

6.2.1 Zoom 35

6.2.2 Diagram Options 36

6.2.3 Snap-to-Point Cursor 41

6.2.4 Screen Mode 41

6.3. Special Calculations 42

6.4. Data Transfer 42

6.5. Store as Reference 44

6.6. Snapshot 47
7. Shortcut Keys 48
8. Trigger Functions 49
9. Maintenance and Error Messages 50
10. Technical Data 51
10.1. Mechanical Dimensions 52
10.2. Battery charging (only specbos 1211-BT) 52
11. CE – Declaration of Conformity 54
12. Certificate of Warranty 55
13. Service 57

1. Introduction

specbos 1211 is an easy to use spectroradiometer for various applications. Its miniaturized shape makes it suitable for laboratory as well as industrial use. The spectroradiometer *specbos 1211* can measure luminance/ radiance as well as illuminance/ irradiance. Furthermore colorimetric data (CCT, chromaticity, color purity, dominant wavelength, CRI) are calculated from the spectral data. Therefore it is suited for the test of light sources as CRT screens, for the measurement of projectors and of room illuminance.
specbos 1211 covers the wavelength range of 350 … 1000 nm and is suitable for low light measurements due to its high sensivity.
The version *specbos 1211 UV* extends the wavelength range to 250 nm.
The indication of the measuring spot on the target in case of luminance/ radiance measurements will be proceeded with a pilot laser circle. Irradiance measurements are done with a cosine corrector head-piece. The software switches automatically to the appropriate measuring mode depending from the attached measuring head.

Acquisition and analysis of data is done by the PC software JETI LiMeS. The connection to the PC is via USB interface (virtual COM port). It is also possible to communicate directly with the instrument without the PC program. Virtual Instruments for LabView are contained on the CD as well as radiometric and spectrometric DLLs. Detailed helping information for both applications is included. Furthermore the instrument can be driven by the SCPI compatible firmware commands. The command list is also available on the CD.

specbos 1211 is available with additional interfaces:

Serial interface	*specbos 1211 RS232*
Bluetooth interface	*specbos 1211 BT*

PC requirements:

- Pentium 4 / AMD Athlon XP or higher, min. 512 MB RAM
- Graphic resolution: 1024*768, 16 bit color depth recommended
- Windows XP (SP3); Vista or Windows 7, Windows 8; Excel 2000 (for data transfer)

The *specbos 1211* packages includes:

- Basic device *specbos 1211* with protection cap
- Cosine corrector head-piece
- Operating instructions
- Tripod
- Transport box
- CD-ROM with PC software JETI LiMeS, DLLs, LabView Virtual Instruments, operating instructions and firmware command list
- USB cable
- Trigger connector

additionally:

specbos 1211-BT

- Bluetooth antenna, bluetooth adapter and a rechargeable lithium polymer battery EasyPack 3.7V (EZPack XL)

specbos 1211-RS

- serial cable
- Power supply 9V

specbos 1211- LAN

- Power supply 5V

2. Operation of Device

2.1. specbos 1211

The instrument will be switched on automatically if the USB connection to the PC is established.
Pressing the illuminated switch switches on the target marking if the instrument is in Radiance mode. Repeated pressing switches the target marking off.

2.2. specbos 1211-BT

The **specbos 1211-BT** will be powered by battery if the wireless interface is used. The battery will be charged when the instrument is connected to the PC via USB. Alternatively it can be charged with the power supply.
The switch on the rearside has the following functions:

- Pressing if instrument is switched off: Switch on the instrument
- Short pressing if the instrument is switched on: Switch on/ off the target marking
- Long pressing if the instrument is switched on: Switch off the instrument
- If the instrument is switched off and connected to power supply or to PC by USB:

▪ Short flashing – battery will be charged
▪ Continuous illumination – battery is fully charged

- If the instrument is switched on:

▪ Continuous illumination with short breaks – battery will be charged
▪ Continuous illumination – battery is fully charged

Remark: The USB connection between PC and instrument needs to be established if the battery shall be charged via USB.

Automatic switch off:

The instrument will be switched off if there is no connection to the PC for more than 15 min., e.g. if the operator forgot to switch it off. If the software LiMeS is running the instrument will be not switched off automatically.
The battery powered **specbos 1211-BT** will be automatically switched off if the defined operating time without any communication is elapsed. The device send in this case a enquire code (0x05).

Battery down:

If the battery charge is below the low value a enquire code (0x05) will be sent, and a timer for time out starts.
After time out the device send again the enquire code and switched power off.

3. Installation of Hardware

3.1. Installation of USB Device

Unpack the spectroradiometer *specbos 1211* carefully and check the delivered parts.

Connect the device to an USB interface of a PC or laptop using the enclosed USB cable.

3.2. Installation of Bluetooth Device (*specbos 1211 BT*)

specbos 1211 BT can be used alternatively via bluetooth or USB. Press the rearside switch until it is shinning in blue.



The package of the device includes the bluetooth antenna. Please connect it to the instrument as it is shown below.
The bluetooth interface is often integrated into modern computers. If your computer is not equipped with it you need to use the bluetooth antenna (included in the delivery).
The software directs you through the installation.

- Click on the symbol

- Click Add a Device



- Click Continue and select JETI *specbos 1211*



- *Click Next*



- Insert the device's pairing code: 0000



The next window finalizes the installation.



3.3. Installation of RS Device (*specbos 1211 RS*)

Connect the device to a PC or laptop using the enclosed RS cable and the power supply (9 V):

3.4. Network settings for specbos 1211 LAN

To communicate with the specbos 1211 LAN via a network connection the specbos device and the controlling PC have to use the same network address space.
The default network setting of the specbos device is set to DHCP (obtain network settings automatically). If a DHCP server is running in your network the device will obtain an IP address from within the local network address space, and no further steps are required.
If no DHCP server is available (e.g. direct connection to a PC) or you want to give the device a fixed IP address for some other reasons, the network setting of the specbos device has to be changed by a tool called "Digi Device Discovery", which is available on the installation CD.

Please note that you must have administrator privileges!

1. Connect specbos 1211 LAN to the power supply and to the LAN (1:1 as well as crossed cables can be used)
2. Go to directory 'Tools\Device Discovery' on the installation CD and run 'dgdiscvr.bat

3. The tool will search all devices in your LAN and display it on the screen



Digi Device Discovery screen with two attached devices (devices are distinguished by their MAC address)

4. Devices, which are not configured properly to be controlled via your LAN, are marked with a red exclamation mark
5. Right-click on the device to configure and select 'Configure network settings' from the menu
6. A window will appear where you can configure the network setting of the specbos device



7. After clicking on 'Save' a message appears that the device must be restarted
8. If no more red exclamation mark is visible, the device is configured properly to work in your LAN

Remark: The IP address of a PC can be found using cmd.exe in the command line and the command ipconfig.

3.5. Installing RealPort Driver

Please note that you must have administrator privileges to install the driver!

If you want to run JETI LiMeS software controlling a specbos 1211 LAN device via a network connection, a special driver has to be installed. This so-called 'RealPort Driver' provides a virtual serial COM-port, which JETI LiMeS and also serial terminal programs can use to communicate.
This chapter describes the installation procedure of the RealPort driver.

1. Go to directory 'RealPort Driver' on the installation CD and run 'setup.exe'
2. Select 'Add a New Device' and click on 'Next'



3. A list with the found network devices will appear. Please select the device a RealPort driver shall be installed and click 'Next'.



4. **If the desired device didn't appear in the list, you have to check the network settings of the device. See chapter "Network Settings For Specbos 1211" for details.**
5. Don't change the suggested settings and click 'Finish' to start the installation.



6. After a while a dialog box should appear that the driver was successfully installed.

3.6. Installation of Driver Software

Please note that you must have administrator privileges to install the device driver!

This chapter describes the installation procedure of the USB driver

3.6.1 Installation under Windows XP

1. Insert CD-ROM delivered with your device into the CD/DVD drive.
2. If Autorun is enabled on your PC the following window appears. Otherwise run install.exe from the CD.



3. Click the Install USB drivers... button and follow the instructions to install the drivers.
4. If a warning window appears that the software has not passed Windows Logo testing, press Continue Anyway.
5. After finishing connect your device to an USB-port.
6. A ‘New Hardware found’ wizard should appear. If it asks to connect to Windows Update answer with No.
7. Select Install software automatically (recommended) and press Next.

8. Windows should complete the driver installation automatically. If a warning window appears that the software has not passed Windows Logo testing, press Continue Anyway.

3.6.2 Installation under Windows Vista and Windows 7

1. Insert CD-ROM delivered with your device into the CD/DVD drive.
2. If Autorun is enabled on your PC the following window appears. Otherwise run install.exe from the CD.



3. Click the Install USB drivers... button and follow the instructions to install the drivers.
4. If a warning window appears that 'Windows can't verify the publisher of this software', click on Install Anyway.
5. After finishing connect your device to an USB-port.
6. Windows should complete the driver installation automatically.

3.7. PC- Software

3.7.1 Installation under Windows

Please note that you must have administrator privileges to install the device driver!

Execute the following steps on the PC to install the software *JETI LiMeS* :

- Start Windows 7/ XP/ Vista
- Insert the CD in the CD-ROM drive
- The following window appears, if the autostart function of Windows is activated.
  Otherwise press install.exe in the Install folder of the CD ROM.



- Click the Install JETILiMeS... and follow the instructions to install the program.

4. Start the Software

- Start Windows and then activate the Start menu
- Select JETI LiMeS under Programs

The software will automatically find the COM port and the baudrate (standard: 921 600 baud) after starting the program, if a spectroradiometer *specbos* is connected to the PC with its USB cable.
In some cases the automatism doesn't work properly, especially if there are other COM ports (Bluetooth serial ports, USB virtual com ports,…) installed on the PC.
The software JETI LiMeS accepts an argument at starting time which defines the COM port to use. If no argument is given (standard) the automatic will be used. Otherwise pass a value from 1 to 256 for the corresponding ports COM1 to COM256.
To set the argument the shortcut which starts the program has to be edited. To edit right-click the 'JETI LiMeS' icon on the desktop and select 'Properties'. The following dialog appears:



Type the number of the COM port to use after the filename of the executable in the 'Target' box (4 for COM4 in this example). Use a space sign between the filename and the COM port number.
If no device could be found on the specified port the software asks to perform an automatic scan.
In case of an error, this error will be displayed (see chapter Maintenance and Error Messages).

About



Click Info/About! shows the following window with the software version, the serial numbers, the used COM port, the baudrate and the firmware version.



Press x to close the window.

5. Measurement

5.1. Procedure



The measurement procedure consists of a first spectra acquisition with a fixed integration time, a subsequent calculation of the best integration time for a well-driven spectrum, a second measurement with this time and a final dark spectrum measurement. In some cases more adaptation steps are necessary. You will be informed about the status of the measurement (Adaption to exposure, Performing measurement) and about the remaining time. The maximum integration time is 60 s, therefore the maximum measuring time for low intensity sources is approx. 120 s (adaption time + max. integration time + max. dark measuring time). The measured spectrum as well as the radiometric, photometric and colorimetric data, calculated from the spectrum are displayed. Furthermore the number of the measurement is shown in the legend.

Following measurements will be shown with their values. Clicking on the spectrum line displays the data of former measurements. A thick line always indicates the actual spectrum.

Pressing Esc can interrupt a started measurement.

5.1.1 Measurement with specbos 1211-BT

The **specbos 1211-BT** will be powered by battery if the wireless interface is used. The battery will be charged when the instrument is connected to the PC via USB. Alternatively it can be charged with the power supply.

The switch on the rearside has the following functions:

- Pressing if instrument is switched off: Switch on the instrument
- Short pressing if the instrument is switched on: Switch on/ off the target marking
- Long pressing if the instrument is switched on: Switch off the instrument
- If the instrument is switched off and connected to power supply or to PC by USB:
  - Short flashing – battery will be charged
  - Illumination off – battery is fully charged
- If the instrument is switched on:
  - Continuous illumination with short breaks – battery will be charged
  - Continuous illumination – battery is fully charged

Remark: The USB connection between PC and instrument needs to be established if the battery shall be charged via USB.

The battery status is shown in the software JETI LiMeS in the title bar.

Automatic switch off:

The instrument will be switched off if there is no connection to the PC for more than 15 min., e.g. if the operator forgot to switch it off. If the software JETI LiMeS is running the instrument will not switched off automatically.

Battery down:

If the battery is down during operation the following window will appear:



After 3 minutes the connection will be cut and JETI LiMeS goes to offline mode. Now it is possible

- to save all previous measured data and finish JETI LiMeS

or

- to connect the instrument to external power (USB or power supply), press CRTL I to reconnect and continue the in measurements with JETI LiMeS.



Operate without software JETI LiMeS

The battery powered **specbos 1211-BT** will be automatically switched off if the defined operating time without any communication is elapsed. The device send in this case a enquire code (0x05).
If the battery charge is below the low value a enquire code (0x05) will be sent, and a timer for time out starts.
After time out the device send again the enquire code and switched power off.

5.1.2 Finishing the Program



The program can be closed by selecting the Quit button or by typing Alt Q on the keyboard. If one or more measurements were not stored the following window appears to avoid data loss.

6. Software Settings

6.1. Measurement Settings

6.1.1 Integration Time

The instruments adapts the integration time automatically to the measuring conditions.

It is possible to hold an once determined integration time for further measurements. This is mainly interesting in case of measuring objects with similar intensity. Simply click the box Hold Integration Time. There will shown a warning if over and underexposure occurs (Couldn't hold integration time). Then a new adaptation will be processed and the time will be hold for further measurements.



In some cases it is desirable to set the integration time to a fixed value. This can be done with CTRL T. Afterwards write the desired time (in ms) into the appearing window.
Following measurements will use this integration time without any adaption.
A suitable value for the integration time can be found after a first measurement with activated adaption by pressing the F12 button (Tint).
Deactivate the fixed integration time function by pressing CTRL T again.

6.1.2 Continuous measurement

If you want to measure continuously you have two options. If you select Continuous Scan and the interval [s] the measurement procedure is like described in chapter 5.1.
If you select Hold Integration Time and Continuous Scan the measurement is without adaption. Normally the integration time at start will be hold for all subsequent measurements.



It will be adapted without warning in case of over or under exposure. This can influence the difference of time between the successive measurements. If you want to get a constant repetition rate you have to use the CTRL T option (fixed integration time).

6.1.3 Change measurement name

The proceeded measurements will be named with consecutive numbers. It is possible to change this standard name.



- Make a right mouse click on the desired measurement name in the legend to open a panel
- Rename changes the measurement name
- Change Plot Options open the following window:



The plot color can be change and also the line style.



- Delete deletes the measurement

- Pressing the DEL key also deletes the actual or marked measurement

There will always appear a confirmation window until the data will be deleted.

6.1.4 Delete Measurements

The active measurement or all measured data can be deleted under the menu point File.
A single measurement can also be deleted with the DEL key after selecting it in the legend with a left mouse click. It is also possible to delete a number of measurements using the CTRL or SHIFT keys in the usual manner. All measurements can be deleted together with CTRL DEL.



There will appear a confirmation window before the data will be deleted.

6.1.5 Calculation Range

The menu point Options/ Calculation Range allows to specify if the radiometric value will be calculated from the entire calibrated wavelength range (specbos 1201 380 … 780 nm; specbos 1211 350 … 1000 nm) or only from the limited (displayed) range (user selected range).



See chapter Spectra Calculations how to change the wavelength range.

6.2. Display Settings

6.2.1 Zoom



Diagrams can be zoomed with the cursor by pressing CTRL. The kind of zoom can be selected in the pop up menu left to the JETI logo. X-Zoom and Z-Zoom is only valid for the spectrum diagram.
Zoom out by pressing RESET below the Zoom pop up menu.
The start and the end of the displayed spectrum can alternatively be adjusted at the screen edge below the diagram with Start of Spectrum and End of Spectrum. In addition of using the up/down arrows, the displayed spectral limits can be typed in using the keyboard number pad. The maximum interval for *specbos 1x01* is between 380 nm and 780 nm. Always the full spectral range of the device is used for a measurement.

Remark: The start and end wavelength settings will be used for the calculation of the radiometric value if its calculation range is set to user selected range.

6.2.2 Diagram Options

Selecting View/ Diagram in the menu bar opens a window, where the display of the spectral data, the xy and u´v´ diagrams, the classification screen or the display of enlarged numerical values can be selected.



- The menu item View/ Diagram/ Raw spectrum allows to display the raw data of the spectrograph. This can be useful sometimes, e.g. if the general characteristics of the measured spectrum outside the calibrated range is of interest. The raw spectrum is the basis for all radiometric calculations.



- The colour coordinate diagrams contain the Planckian curvature for orientation. The actual measuring values will be indicated in the diagrams.

In both colour diagrams zooming is possible with the Zoom function appearing left of the JETI logo.

- It is possible to switch on and off the dominant wavelength scale at the curved border of both colourimetric diagrams with Options/ Diagrams/ Labelled xy- and u´v´-diagram.



- The Rank view shows the result of the classification after defining and enabling it in the Extra/ Rank… menu point. (Chapter Fehler: Referenz nicht gefunden)
- Numeric values switches to a large display mode of selected values. The kind of data can be selected in the pop up menu above the values.



The number format for luminance/ radiance, illuminance / irradiance, luminous/ radiant flux (with specbos 13x1) and luminous/ radiant intensity (with specbos 1401) can be change between scientific and floating point notation.



The last item of the View menu is the data table (View/Diagram/ Table view). It can be used to display the measuring data and to save them in .xls or .csv files.



- Select Export/ Setup Output and choose the desired data to be transferred into the table.



Remark: The boxes Spectral Radiance/ Irradiance/ Radiant Flux/ Radiant Intensity, Luminance/ Illuminance/ Luminous Flux/ Luminous Intensity and Radiance/ Irradiance/ Radiant Flux/ Radiant Intensity appear in dependence from the attached measuring head.

- In case of selection of the spectral data the user has to click on the desired wavelength step width for the transfer (1 or 5 nm). Line Offset in Table shifts the transfered data downwards. Finally click on the OK button to close the window.



Click Transfer to export the data to a table (F8 shows the table)

- The marked measurement will be transferred. It is possible to mark several measurements simultaneously by using CTRL or Shift as usual; using CTRL marks single measurements and Shift marks a block of measurements.
- If a measurement was already identified by an individual name this name will be used as column header in the table. If not changed the automatically generated measurement number will be used.
- It is also possible to store loaded reference spectra in the same manner.

- If the button Auto is activated, all following measurements will be transferred automatically.

The cells of the first lines can be edited. The number of these lines has to be selected in the “Line Offset” setting.
See chapter Shortcut Keys for shortcut keys to switch between different display modi.

6.2.3 Snap-to-Point Cursor

Single data points of the acquired spectrum can be viewed using the Snap-to-Point Cursor option, if the spectral diagrams are displayed. The respective wavelength and the spectral value of the selected data point are displayed below the wavelength axis.

6.2.4 Screen Mode

There are different spectrum display options that can be selected under the View menu:



All Measurements	All measured spectra are displayed in the diagram.
Active Measurement	Only the active measured spectrum is displayed in the diagram.

6.3. Special Calculations



6.4. Data Transfer

Measuring data transferred into the table view (chapter Display Settings) can be stored in csv, xls or xlsx file format (Excel 97 or higher).



Remark: Excel installation isn't necessary.

Select Export/ Setup Output and choose the desired data to be transferred into the table.

Remark: The boxes Spectral Radiance/ Irradiance/ Radiant Flux/ Radiant Intensity, Luminance/ Illuminance/ Luminous Flux/ Luminous Intensity and Radiance/ Irradiance/ Radiant Flux/ Radiant Intensity appear in dependence from the attached measuring head.

In case of selection of the spectral data the user has to click on the desired wavelength step width for the transfer (1 or 5 nm). Line Offset in Table shifts the transferred data downwards. Finally click on the OK button to close the window.



Use Export/ Save Table, select the file name, format and storage location of the file and press OK.

Remark: Reference Spectra can be directly used for Spectra Calculations (see chapter Spectra Calculations).

Click Transfer to export the data to a table (F8 shows the table). The marked measurement will be transferred.

6.5. Store as Reference



The items File in the menu bar allows to store measured spectra as a reference for further measurements. There can be used two formats – Character Seperated Values (CSV, file extension .csv) or the Galactic SPC file format (GRAMS compatible, file extension *.spc)*.

Remark: Reference Spectra can be directly used for Spectra Calculations (see chapter Spectra Calculations).

A spectrum can be stored by clicking File/ Save as reference. First type in the name of the file and select the destination for storage. Afterwards user comments (memo) and the operators name can be written into the following windows.



If previously saved reference spectra should be displayed, click on File/ File manager. Spectra of both formats can be loaded into the list or unloaded from it. The information data of an actual file are

displayed below the file list. Click into the column left of the file name to mark the desired spectra.
The plot options of each reference file can be changed by double click on the file name in the list. Then close the window. Now all marked spectra are shown in the diagram. If you click on a spectrum the corresponding measuring values are shown on the right side of the diagram.

Remark: It is only possible to load reference spectra of the same measurement mode which is selected. In offline mode it is necessary to switch manually to the appropriate mode.

To load reference spectra from other instruments into JETI LiMeS, you have to create a csv-file in the format shown below. For identification the first line has to made out to “MODEL, SB1201”. Every line has to end with new line. The TYPE line must be the measurement mode Radiance, Irradiance, Radiant Flux or Radiant Intensity. The start and end wavelength have to be between 380 and 780 nm and the step width is restricted to 1 nm (interpolate if necessary).
The operator line can have at most 63 characters and the Memo line 129 characters. The line integration time is necessary, but the quotation is irrelevant.

Remark **The decimal symbol is depending from the settings of the computer.**

The easiest way to create such file is to store an arbitrarily measured spectrum in CSV format and use this file as basis for the new one by overwriting the appropriate lines. This can be done in Excel. Afterwards it can again be stored in CSV format.




```
MODEL,SB1201
TYPE,Radiance
Start Wavelength [nm],380
End Wavelength [nm],780
Number of points,401
Integration Time [ms],339
Operator,Bo
Memo,daylight
Date,04/13/2007
Time,03:10pm

Wavelength,Spectral Radiance [W/(sr*sqm*nm)]
 380,3.031103E-02
 381,2.804247E-02
 382,2.635635E-02
 383,2.559559E-02
 384,2.608207E-02
 385,2.724398E-02
 386,2.849134E-02
 387,2.999738E-02
 388,3.203355E-02
 389,3.397759E-02
 390,3.474155E-02
 391,3.389907E-02
 392,3.251747E-02
 393,3.100938E-02
 394,3.028535E-02
 395,3.103387E-02
 396,3.338305E-02
```

6.6. Snapshot

In the menu Extra/ Snapshot it is possible to store the actual screen in a file or to print it.



You can choose between the full screen or the diagram only. JPG, BMP and PNG files are possible. In case of printing you have to select the printer settings.
The alternative keys are F11 and Shift F11, respectively.

7. Shortcut Keys

F1	About box (including product/ vendor ID, virtual COM port number, baudrate, firmware version)
F2	Display of spectrum
F3	Display of xy diagram
F4	Display of u´v´diagram
F5	Display of raw spectrum (dark signal corrected)
F6	Rank view
F7	Large display of numerical values
F8	Open the data table
F9	Start of measurement
F11	Snapshot into file
Shift F11	Snapshot to printer
F12	Display of actual integration time and maximum counts in spectrum (including dark counts)
Alt Q	Finish the program
CTRL D	Open the distance panel of luminous intensity measurement
CTRL Del	Clear all measurements (with accepting window)
CTRL T	Open/ Close the panel for fixed integrating time
Del	Clear actual/ activated measurement
ESC	Abort a running measurement
CTRL + left mouse key	Zoom in (xy and u´v´diagrams)
Space	Start of measurement (only if measurement button is active)

8. Trigger Functions

It is possible to trigger the measurement externally and to initiate a flash of a pulse light source.
The trigger female connector at the rear side of the instrument has the following pin out:

Mini DIN 8



Mini DIN 4



Pin out (view to female connector of the instrument):
3 Lamp out 5 V TTL signal (flash lamp trigger)
5 Measuring trigger input
6 not used
8 Ground

The fitting male connector is included in the scope of the device delivery.

External Control of Measurement

A measurement can be initiated externally by a short cut between pin 5 and 8. This can be done e.g. by a foot push-button. Furthermore it is possible to use a TTL signal to start a measurement. This is done with the falling edge of the signal.
Both triggering versions act similarly as pressing the green Measurement button of the software.

See the firmware description to change the settings.

9. Maintenance and Error Messages

The instrument needs no permanent maintenance, if you use it carefully. It is recommended to recalibrate it every year. Ask your dealer or the producer (see chapter *13*) for details.

Error message	Reason	Removal
Device not found! Switched to offline-mode	Device not connected or USB driver not installed correctly.	Connect the device to the PC or check the installation of the device driver (see install.txt on Setup-CD).
Could not read calibration data from device!	It was not possible to read the data stored inside the instrument.	Contact your supplier.
Could not write calibration data!		Repeat calibration process.
Wrong lamp file!	Lamp file was not readable or did not fit the requirements.	Change lamp file or ensure the correct file access.
Overexposure! Measurement failed.	The measuring object overexposed the instrument.	Reduce the measuring intensity by calibrated filters.
Could not read parameter.	The software can not read the necessary parameters from the instrument.	Contact your supplier.
Could not read file!	It was not possible to read a selected reference file.	Check the readability of the file.
Could not write file!	It was not possible to write a measured file as reference.	
Error on USB-Transfer	It was not possible to read or write data via USB	Check the USB-connection and restart the software

10. Technical Data

Applications	Measurement of diffuse light sources, screens etc., of room illuminance and of lamps
Spectral range	350 ... 1000 nm (optional 250 …. 1000 nm)
Spectral resolution (Rayleigh)	4.5 nm
Wavelength accuracy	± 0.5 nm
Digital spectral resolution	1.8 nm
Digital electronic resolution	16 bit A/D (15 bit used, 14 bit displayed)
Measuring values	Spectral radiance/ spectral irradiance Integral luminance/ integral radiance/ Integral illuminance/ integral Irradiance Chromaticity x,y; u´,v´ Correlated Color Temperature Dominant wavelength, color purity Color Rendering Index Circadian metrics Photosynthetically Active Radiation
Measuring range luminance	tbd.
Measuring range illuminance	tbd.
Viewing angle in luminance mode	1.8 °
Measuring distance/ diameter in luminance mode	20 cm - ∅ 6 mm; 100 cm - ∅ 30 mm
Accuracy photometric value	± 5 % (@ illum. A)
Reproducibility of photometric value	± 2 %
Color chromaticity accuracy	± 0.002 x, y (@ illum. A)
Color reproducibility	± 0.0005 x, y
CCT reproducibility	± 20 K (@ illum. A)
Integration time range	5 ms ... 60 s
Dispersive element	Diffraction grating
Light receiving element	2048 pixel binned CCD array
Operating conditions	Temperature 10 ... 40 °C Humidity < 85 % relative humidity at 35 °C
Power supply	Hub powered (**specbos 1211-BT** will be powered by battery if the wireless interface is used)
PC interface	USB 2.0 fullspeed (12 Mbit/sec) Bluetooth (**specbos 1211-BT**) RS232 (**specbos 1211-RS**)
Dimensions	180 x 82 x 53 mm³ (basic unit)
Weight	450 g (basic unit)

Pilot laser	Laser class 1, λ= 650 … 670nm (classific. Accord. to EN60825-1/ Oct. 2003)
Transfer module R47F2M03GX	Free2move AB (only **specbos 1211-BT**) FCC identifier

10.1. Mechanical Dimensions

The following drawings show the positions of the threads downside the device and some general dimensions of the instrument.

specbos 1211:



10.2. Battery charging (only specbos 1211-BT)

The battery can be charged using the power supply or using the USB port of a PC. In this case the instrument has to be installed via this interface to the computer.
The menu point Info/ Battery status shows the charging level of the battery:



The charging level can also be seen in the active title bar of the main window.



If the instrument is in charging status the following window appears:



The battery is fully charged if the illuminated switch isn't flashing any more.

11. CE – Declaration of Conformity

No : **No : 101261076/ 101261077/ 101261078**
We :

JETI Technische Instrumente GmbH
Tatzendpromenade 2
07745 Jena
GERMANY

declare that the product serie

Spectroradiometer

specbos1211

to which this declaration relates is in conformity with the requirements of following documents:

- EU Electromagnetic Compatibility (EMC) Directive (December 2004) 2004/108/EC
- Low voltage directive 2006/95/EC

EU Harmonised standards:

EN 61326-1 (2006-10)

IEC 61000-4-2, IEC 61000-4-3, IEC 61000-4-4, IEC 61000-4-5, IEC 61000-4-6, IEC 61000-4-11

CISPR 11

The conformity of the product with the standards and directives mentioned above, is confirmed by the CE sign.

Jena, January 2011

JETI
Technische Instrumente GmbH
Tatzendpromenade 2
07745 Jena
Tel.: 03641/225680
Fax: 03641/225681

Dr. Steffen Görlich
General Manager

12. Certificate of Warranty

Certificate of Warranty for

Model: Spectroradiometer

Type: specbos 1211

JETI Technische Instrumente GmbH (referred to as JETI) hereby warrants this equipment as follows:

If any part of this unit (except as described below) fails due to poor workmanship or material (determined by JETI) within TWO (2) years from date of delivery, that part will be exchanged at no charge.

This warranty is valid only when the unit is installed and adjusted according to factory specifications and serviced by competent authorized personnel.

JETI does not assume responsibility for any of the following, all of which are excluded from the coverage of this warranty:

1. Damage due to ordinary wear and tear, abusive use, or lack of proper maintenance
2. Damage due to harsh mechanical shock, e.g. falling to the floor
3. Loss or damage due to adverse environmental conditions or acts of God
4. Loss of wages or income due to repair, replacement, malfunction or damage

Warranty becomes void if serial number is removed or defaced, or the instrument was opened by the customer.

If a defect appears which the customer feel is covered by this warranty, a written notice describing the defect must be sent to JETI's office at the current address of record.

Upon receipt of customers written report of a defect, if the defective items are covered by this warranty, JETI will repair or replace it at no charge to the customer, within 30 days after receipt of the returned unit (provided there are no labor problems or materials shortages to cause delays). The choice between repair and replacement shall be determined by JETI based on actual conditions or circumstances. JETI reserves the right to substitute new and improved equipment or parts at any time. The obligation to replace defective parts does not require replacement of the complete unit.

NO OTHER WARRANTY EXPRESSED OR IMPLIED IS APPLICABLE TO THIS UNIT .

This warranty shall be in effect for a period of 24 months, beginning one week after the date of delivery.

13. Service

Please contact in case of any question or technical problem:

JETI Technische Instrumente GmbH
Tatzendpromenade 2
D-07745 Jena
Tel. +49 3641 225 680
Fax +49 3641 225 681
e-mail: support@jeti.com
Internet: www.jeti.com

Copyright (c) 2012 JETI Technische Instrumente GmbH. All rights reserved.
Software and operating instruction are delivered with respect to the License agreement and can be used only in accordance with this License agreement.
The hard and software as well as the operating instruction are subject to change without notice. JETI Technische Instrumente GmbH assumes no liability or responsibility for inaccuracies and errors in the operating instruction.
It is not allowed to copy this documentation or parts of it without previous written permission by JETI Technische Instrumente GmbH.

16 January 2013

Table of Contents

1. Introduction 11

2. Operation of Device 13

2.1. specbos 1211 13

2.2. specbos 1211-BT 13

3. Installation of Hardware 15

3.1. Installation of USB Device 15

3.2. Installation of Bluetooth Device (specbos 1211 BT) 15

3.3. Installation of RS Device (specbos 1211 RS) 19

3.4. Network settings for specbos 1211 LAN 19

3.5. Installing RealPort Driver 21

3.6. Installation of Driver Software 24

3.6.1 Installation under Windows XP 24

3.6.2 Installation under Windows Vista and Windows 7 25

3.7. PC- Software 26

3.7.1 Installation under Windows 26

4. Start the Software 27

5. Quick Start 29

6. Measurement 31

6.1. Procedure 31

6.2. Measurement with Additional Interfaces 32

6.2.1 Measurement with specbos 1211-BT 32

6.2.2 Finishing the Program 34

6.3. Measuring Modi 34

6.3.1 Luminance Mode 34

6.3.2 Illuminance Mode 36

6.3.3 Luminous Flux Mode – specbos1301 and 1311 36

6.3.4 Luminous Intensity Mode – specbos1401 37

6.4. Special Measurements 39

6.4.1 Small Luminance Sources 39

6.4.2 Pulsed Sources 40

6.4.3 Luminous Flux measurement mode with self absorption correction 42

6.5. Special Calculations 46

6.5.1 Colour Rendering Index (CRI) 46

6.5.2 Circadian Metrics 47
6.5.3 Photosynthetically Active Radiation (PAR) 48
6.5.4 LED Values 50
6.5.5 RGB Values 50
6.5.6 Colour Values 52
6.5.7 Spectra Calculation 52
6.5.8 Ratio Calculation 55
6.5.9 Metamerism 56

7. Software Settings 57

7.1. Measurement Settings 57
7.1.1 Integration Time 57
7.1.2 Continuous measurement 58
7.1.3 Change measurement name 58
7.1.4 Delete Measurements 59
7.1.5 Averaging 60
7.1.6 Observer 60
7.1.7 Calculation Range 60
7.1.8 SI Units/ Imperial Units 61
7.1.9 Number Format 61
7.1.10 Target 61

7.2. Display Settings 62
7.2.1 Zoom 62
7.2.2 Diagram Options 62
7.2.3 Snap-to-Point Cursor 68
7.2.4 Screen Mode 68

8. Selection Procedures 69

8.1. Pass/ Fail Monitoring 69

8.2. Classification (Ranking) 70

9. Data Storage 75

9.1. Data Transfer 75

9.2. Store as Reference 77

9.3. Snapshot 80

10. Calibration 81

11. Shortcut Keys 84

12. Trigger Functions 85

13. See and Click 86

13.1. Significance of the color Code 86

13.2. Software Installation 86

13.3. Start the Program 92
13.4. Measuring Mode Luminance 93
13.5. Illuminance mode 96
13.6. Luminous Flux mode – specbos13x1 98
13.7. Luminous Intensity mode – specbos1401 99
13.8. Export 101
13.9. Finishing the Program 104
14. Technical Data 105
14.1. Mechanical Dimensions 107
14.2. Battery charging (only specbos 1211-BT) 107
15. Maintenance and Error Messages 109
16. CE – Declaration of Conformity 111
17. CE – Declaration of Conformity 112
18. Certificate of Warranty 113
19. Service 115