# Quick Manual LiMeS

- Connect specbos 12x1 to a PC or Laptop
- Start JETI LiMeS under Programs in the Start menu (software and driver installation is described in the operation manual)




- Click the Target circle button and adjust the instrument viewing to the desired position

- Click the Measurement button to start the measurement
- Maximum measuring time = 120 s
- Press Esc to interrupt a running measurement in case of problems
- Spectrum and measuring values are shown
- Click View/ Diagram/ Numeric values in the menu bar to open a window, which shows the measuring values in a jumbo format



- Select the desired combination of values from the ring control




- Switch between SI and imperial units using the Options/ Photometric units menu point
- Measuring data transferred into the table view can be stored in csv or xls file format.
- Use Export/ Save Table, select the file name, format and storage location of the file and press OK.




- Proceed further measurements by clicking on the Measurement button again
- Scroll between different measurements in the legend by clicking on the name

## Change measuring mode to illuminance

- Attach the diffusor cap to the device
- Use as program before (except for target circle)

## Shortcut Keys

| | |
|---|---|
| F2 | Display of spectrum |
| F3 | Display of xy diagram |
| F4 | Display of u´v´diagram |
| F7 | Large display of numerical values |
| F9 | Start of measurement |
| Space | Start of measurement (only if measurement button is activated) |
| ESC | Abort a running measurement |
| Del | Clear actual/ activated measurement |
| CTRL Del | Clear all measurements (with accepting window) |
| Alt Q | Finish the program |